


# 15B/17B/18B Digital Multimeters Quick Reference Guide

⚠ See Users Manual for "Safety Information" and complete operating information.


## Fuse Test

0.0 - 0.1Ω = OK


0.099 - 1.01 kΩ = OK




## Voltage $\tilde{V}$ $\bar{V}$ $mV$




## Resistance Ω




## Continuity $\text{diagonal line}$




## LED Test (18B Only)




## Current $\tilde{A}$ , mA, $\mu A$







## Capacitance $\mu F$




## Temperature (17B Only)




### Diode Test →





### Duty Cycle % (17B Only)



### Frequency (Hz) (17B Only)




### Relative Δ (Zero) (17B Only)



EXIT  
REL

### HOLD



### ToolPak/MH10 (Optional)

