

**LD-50/70/100**



**Features :**

- Battery Installation and Replacement
- Turn On/Off Button
- Backlight On/Off
- Self Calibration Function
- Single/Continuous/Area/Volume Measurement

**Technical Data**

ITEM	LD 50	LD 70	LD 100
Working Range	0.05-50m	0.05-70m	0.05-100m
Precision	$\pm(2\text{mm}+d*1/10000)^*$		
Continuous Measurement	ok		
Area/Volume Measurement	ok		
Pythagorean Measurement	ok		
Add And Subtract Measurement	ok		
Area & Volume Addition/Subtraction	ok		
Min/Mix Value	ok		
Self-Calibration	ok		
Laser Level	II		
Laser Type	630-670nm, <1mW		
Max Storage	99 Units		
Automatically Cut off Laser	20s (single measurement)		
Auto Power-off	150s		
Battery Life	4000/8000 times (carbon-zinc battery/ alkaline battery)		
Storage Temperature	-20°C~60°C		
Working Temperature	0°C~40°C		
Storage Humidity	20%~80%RH		
Battery	2X1.5V AAA		
Dimension	108x50x25mm		

